| Engine Record General Information | | | | | | |
|--|--------------------|--------------|--|--|--|--|
| M112TC SN Manufacturer Lyc. Serial L-285-69A | 13266 | | | | | |
| Manufacturer Lyc. | Model 70-360-CIA6D | | | | | |
| Serial L -285-69A | Type Certificate | | | | | |
| This engine is currently installe | | | | | | |
| Minimum Octane Fuel | Oil Grade Summer_ | Winter | | | | |
| Magneto Time | Point Setting | Firing Order | | | | |
| Spark Plug Gap | | | | | | |
| Manufacturer's Recommended (| Overhaul at hours | | | | | |

| DATE 19 <i>56</i> | RECORDING TACH TIME | TODAYS FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.) |
|----------------------|---------------------------|------------------|-----------------------------|--|
| 7-12 | 1506.16 | <u> </u> | 1506.16 | CHange oil 7975 50 wt acoshell Repl. variatherm with Serviceble |
| <u> </u> | <u> </u> | | | 53E19600 C/W 3B518C - Rig throttle, |
| | | | | LOG# 6114 FAA REPAIR STATION # ZNORO29M PRESCOTT AIRPORT |
| | | | Ja | 2020 CLUBHOUSE DR. PRESCOTT, ARIZONA 86301 520-717-1680 |
| | | | 2m | 3R029m |
| | | | | |
| | | | | |
| | | | | |

| DATE VUUG 19 | RECORDING TACH TIME | TODAYS FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.) |
|--------------------|---------------------------|------------------|-----------------------------|--|
| 1-20-00 | 2045 | | 20460 | ENGIME REMOVED FROM |
| | | | | AC NIIZTO THIS DATE |
| | | | | ENGIME REMOVED PROM ALC NIIZTC THIS DATE CO.Baml APSB605454 |
| | | | | |
| | X- | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

© 1991 ASA